



**Photo 1 – Substantial Damage to Left Wing (Photo courtesy of FAA)**



**Photo 2 – Left Wing Spar Damage (Photo Courtesy of FAA)**