



Photo 1 – Airplane with Nose Gear Collapsed Near Runway Edge (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Right Wing (Photo Courtesy of FAA)



Photo 3 – Substantially Damaged Right Wing (Photo Courtesy of FAA)