



Photo 1 – View of destroyed airplane (photo courtesy of the FAA)



Photo 2 – Front view of propeller blade 1 (photo courtesy of the FAA)



Photo 3 – Back view of propeller blade 1 (photo courtesy of the FAA)



Photo 4 – Side view of propeller blade 2 (photo courtesy of the FAA)