



Photo 1 – Airplane Nosed Over (Photo Courtesy of FAA)



Photo 2 – Failed Nose Landing Gear Bungee (Photo Courtesy of Operator)



Photo 3 – Oil Residue on Nose Landing Gear Bungee (Photo Courtesy of Operator)