



Photo 1 – Front view of right wing removed from fuselage (Photo courtesy of the FAA)



Photo 2 – Damage to left rear side of fuselage (Photo courtesy of the FAA)