



Photo 1 – View of damage to left wing spar, ribs and aileron (Courtesy of FAA)



Photo 2 – View of damage to horizontal stabilizer and rudder (Courtesy of FAA)