



Photo 1 – View of damage to right wing, vertical stabilizer and rudder (Courtesy of FAA)



Photo 2 – View of damage to left wing, vertical stabilizer and rudder (Courtesy of FAA)