



Photo 1 – Airplane with Partially Collapsed Nose Wheel (Photo Courtesy of Operator)



Photo 2 – Substantially Damaged Firewall (Photo Courtesy of Operator)



Photo 3 – Propeller Strikes on Runway (Photo Courtesy of Operator)