



Photo 1 – Airplane Nosed Over (Photo Courtesy of FAA)



Photo 2 – Tire Marks Leading Off Runway (Photo Courtesy of FAA)



Photo 3 – Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)