



Photo 1 – Left view of damaged vertical stabilizer (Photo courtesy of the FAA)



Photo 2 – Right view of damaged vertical stabilizer (Photo courtesy of the FAA)



Photo 3 – Close up view of damage to the vertical stabilizer (Photo courtesy of the FAA)