



Photo 1 – Front left view of damage to wing and aileron area (Photo courtesy of the NTSB)



Photo 2 – Rear view of left wing damage (Photo courtesy of the NTSB)