




**Photo 1 – Substantially Damaged Firewall (Photo Courtesy of FAA)**



**Photo 2 – Forward View of Firewall (Photo Courtesy of FAA)**