



Photo 1 – View of airplane from side (photo courtesy of the FAA)




Photo 2 - View of firewall damage (photo courtesy of the FAA)