



Photo 1 – Substantially Damaged Right Wing (Photo Courtesy of FAA)



Photo 2 – Airplane Next to Highway (Photo Courtesy of FAA)