



**Photo 1 – View of airplane from front (photo courtesy of the FAA)**



**Photo 2 - View of wing root damage (photo courtesy of the FAA)**