



Photo 1 – View of damage to main rotor hub, blade grip (Courtesy of FAA)




Photo 2 – View of damage to main rotor hub (Courtesy of FAA)




Photo 3 – View of damage to main rotor hub (Courtesy of FAA)