



Photo 1 – View of right side fuselage damage (Photo courtesy of the FAA)



Photo 2 – View of right damaged lift struts (Photo courtesy of the FAA)