



Photo 1 – Airplane Upside Down with Damaged Lift Strut (Photo Courtesy of FAA)



Photo 2 – Accident Location Circled in Yellow (Photo Courtesy of FAA)



Photo 3 – Substantially Damaged Fuselage (Photo Courtesy of FAA)