



Photo 1 – Aerial view of airplane prior to runway (photo courtesy unknown)



Photo 2 – View of damaged left wing strut (photo courtesy unknown)