



Photo 1 – View of accident site (courtesy of the operator)



Photo 2 – View of front of fuselage (courtesy of the operator)



Photo 3 – View of empennage (courtesy of the operator)



Photo 4 – View of bottom of fuselage (courtesy of the operator)