



Photo 1 – View of right side of airplane (courtesy of the FAA)



Photo 2 – View of right side of airplane (courtesy of the FAA)



Photo 3 – View of right side horizontal stabilizer with ice accumulation (courtesy of the FAA)



Photo 4 – View of left side of airplane (courtesy of the FAA)



Photo 5 – View of left side of airplane (courtesy of the FAA)



Photo 6 – View of light pole (courtesy of the FAA)



Photo 7 – View of light pole impact mark (courtesy of the FAA)




Photo 8 – Google Earth diagram of approximate accident site measurements (courtesy of the NTSB)