



Photo 1 – View of damage to fuselage aft bulkhead (Courtesy of FAA)



Photo 2 – View of damage to left horizontal stabilizer (Courtesy of FAA)