



Photo 1 – Airplane on Runway with Landing Gear Retracted (Photo Courtesy of FAA)



Photo 2 – Damage to Underside of the Fuselage (Photo Courtesy of FAA)



Photo 3 – Landing Gear Handle in the UP Position (Photo Courtesy of FAA)