



Photo 1 – View of airplane from front (photo courtesy of the FAA)



Photo 2 - View of the left wing damage (photo courtesy of the FAA)