



Photo 1 – Damage to fuselage (Photo courtesy of the FAA)



Photo 2 – Rear view of damaged right wing and aileron (Photo courtesy of the FAA)