




**Photo 1 – View of airplane from the right (photo courtesy of the FAA)**



**Photo 2 - View of elevator damage (photo courtesy of the FAA)**