



Photo 1 – View of damage to right wing (Courtesy of FAA)



Photo 2 – View of damage to left wing (Courtesy of FAA)