

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Fremont County Airport, Canon City State: CO

ZIP: 81240 Country: USA

Latitude: 38-25-42.8168N Longitude: 105-06-24.6759W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 01/28/2017 Local Time: 2:45 p.m.
mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: 16GL

Manufacturer: Great Lakes

Model: 2T-1A-2

Serial Number: 0772

Year of Manufacture: 1977

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 1800 lbs

Weight at Time of Accident/Incident: 1747 lbs

Number of Seats: 2 Flight Crew Seats: _____

Cabin Crew Seats: 1 Passenger Seats: 1

Number of Engines: One

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
- ☒ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

☐ Tricycle

☐ Amphibian

☐ Emergency Float

☐ Float

☐ Hull

☐ Other Launch/Recovery System

☐ None

☒ Tailwheel

☐ High Skid

☐ Skid

☐ Ski

☐ Ski/Wheel

☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Liquid Rocket
- ☐ Turbo Shaft
- ☐ Solid Rocket
- ☐ Turbo Prop
- ☐ Hybrid Rocket
- ☐ Turbo Jet
- ☐ None
- ☐ Turbo Fan
- ☐ Unknown
- ☐ Electric

Fuel System Type (Reciprocating)

☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	AEIO-360-B1G6	L-16851-51A		180	1189.65	55.23	315.23
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 08/19/2016
mm/dd/yyyy

Airframe Total Time: 1124.3 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell

Model: HC-C2YK-4CF/FC7666A-2

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK

Model or Part No.: E-01

TSO No.: ☐ C91 (121.5 MHz) ☒ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Gail Schmidt (Previously Claremont)City: FlorenceState: COZIP: 81226Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☒ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Fremont County AirportDistance From Airport Center: .1 smAirport Identifier: 1V6Direction From Airport: n/a degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 5442 ft. msl**Runway Information**Runway ID: 11 (L/R/C) Length: 5399 ft Width: 75 ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☒ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Gail City of Residence: Florence
 Middle Initial: M State: CO ZIP: 81226
 Last Name: Schmidt (formerly Claremont) Country: USA
 Age at time of Accident/Incident: 58 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☒ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☒ 5-point</td> <td>☒ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☒ 5-point	☒ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☐ 4-point	☐ 4-point																
☒ 5-point	☒ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Flight Instructor</td> <td>☒ Commercial</td> <td>☐ US Military</td> </tr> <tr> <td>☐ Private</td> <td>☐ Recreational</td> <td>☐ Airline Transport</td> <td>☐ Foreign</td> </tr> <tr> <td>☐ Student</td> <td>☐ Sport</td> <td>☐ Flight Engineer</td> <td></td> </tr> </table>				☐ None	☐ Flight Instructor	☒ Commercial	☐ US Military	☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign	☐ Student	☐ Sport	☐ Flight Engineer			
☐ None	☐ Flight Instructor	☒ Commercial	☐ US Military														
☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign														
☐ Student	☐ Sport	☐ Flight Engineer															
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>07/27/2016</u> mm/dd/yyyy														

Medical Certificate Limitations

Must have available glasses for near vision

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:
07/02/2015
 mm/dd/yyyy

Flight Review Aircraft

Make: Bellanca

Model: 14-19-3A

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	---	--	--

Type Ratings

Student Endorsements (Include dates)

Received my tailwheel endorsement when I was a student in a Cessna 140 - 12/15/2012

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	779	62	773	5	24		15			
Pilot in Command (PIC)	639	62	634	0	18		11			
Time as Instructor	0	0	0	0	0					
This Make/Model										
Last 90 Days	25	15	25							
Last 30 Days	6	3	6							
Last 24 Hours	1	1	1							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☐ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☐ Commercial
 ☐ US Military
☐ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None
 ☐ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☐ N/A
☐ Special Issuance

Date of Last Medical

____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review
 or Equivalent, Including
 FAR 121/135 Checks: _____
 mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☐ Instrument Helicopter
☐ Airplane Multi-Engine
 ☐ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate
 number of hours in each box)

All
Aircraft

This Make
& Model

Airplane
Single
Engine

Airplane
Multiengine

Night

Instrument

Actual

Simulated

Rotorcraft

Glider

Lighter
Than Air

Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					Seat Occupied ☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs							
Crew Name and Address First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					Seat Occupied ☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		Injury ☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs							
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints	Age		
First Name: <u>Ronald</u> City : <u>Colorado Springs</u> Middle Initial: <u>J</u> State: <u>CO</u> ZIP: <u>80907</u> Last Name: <u>Johnson</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other		☐ Left ☒ Center ☐ Right ☐ Unknown Row: <u>Front</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown		
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown		
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown		
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown		

FLIGHT ITINERARY INFORMATION					
Last Departure Point Airport ID: <u>1V6</u> City: <u>Canon City</u> State: <u>CO</u> Country: <u>USA</u>		Time of Departure Time: <u>1:50 p.m.</u> Time Zone: <u>MST</u>		Destination Airport ID: <u>1V6</u> City: <u>Canon City</u> State: <u>CO</u> Country: <u>USA</u>	
Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown					
Type of ATC Clearance/Service (Check all that apply) ☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise ☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA					
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special ☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area ☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown ☐ Class D ☐ Prohibited Area ☐ TRSA ☐ FAR 93 ☐ Class E ☐ Restricted Area					
				Altitude of In-Flight Occurrence: <u>5442</u> ft msl	
WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE					
Source of Pilot Weather Information (Check all that apply) ☐ National Weather Service ☐ Company ☐ Flight Service Station ☐ Military ☐ TV/Radio ☐ Internet ☒ Automated Report ☐ None ☐ Commercial Weather Service (DUATS) ☐ Unknown ☐ On-Board Weather			Weather Observation Facility Facility ID: <u>1V6</u> Observation Time: _____ Time Zone: <u>MST</u> Distance from Accident Site: <u>.4</u> nm Direction from Accident Site: <u>120</u> degrees true		
Basic Conditions ☒ VMC ☐ IMC ☐ Unknown		Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night			
Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered Lowest Cloud Condition Height _____ ft agl		Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown Ceiling Height _____ ft agl		Temperature: _____ (C) or <u>56</u> (F) Dew Point: _____ (C) or <u>10</u> (F) Altimeter Setting: <u>30.23</u> in. Hg or _____ MB	
Wind Direction ☐ Variable -or- Direction: <u>120</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: _____ kts	Wind Gusts ☐ Not Gusting -or- Speed: _____ kts	Visibility <u>P6SM</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: <u>6198</u> ft		
Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☐ N/A ☐ Unknown		Type of Precipitation (Check all that apply) ☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals		Restriction to Visibility (Check all that apply) ☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown	
Icing Forecast Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown		Icing Actual Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☒ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown		Turbulence Type (Check all that apply) ☐ None ☐ Clear Air ☒ Terrain-Induced ☐ Convective Turbulence Severity ☒ Light ☐ Moderate ☐ Severe ☐ Extreme	
NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident: 					

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None
☐ Minor
☒ Substantial
☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Fire at Unknown Time
☐ Unknown

Aircraft Explosion

- ☒ None
☐ In-Flight
☐ On-Ground
☐ Both Ground and In-Flight
☐ Explosion at Unknown Time
☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Damage was incurred to the lower side of the lower left wing ribs - minor wrinkling of the leading edge skin. Lower left aileron is buckled approximately mid span. Upper left and right wings have compression damage primarily forward of the front spar and aluminum leading edges. Center section appears to have damage limited to the leading edge and nose ribs only. Right hand cabane struts are buckled from compression loads. Vertical stabilizer and rudder were deformed from compression loads. Left wheel assembly failed due to side loads. Left brake caliper torn loose from brake torque plate and rotated aft approximately 180 degrees. Propeller strike in soft dirt. Damage to propeller appears to be limited to nicks in the leading edges of both blades; propeller track not checked, but blades do not appear to be bent aft.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and and location, services obtained, and intended destination. Provide as much detail as possible.

On 1/28/2017 a friend/co-worker stopped by the airport hoping for a chance to go flying with me. He flew with me one other time last fall. I was cleaning off the dust and bugs and on my Great Lakes Biplane when he arrived. We checked the weather for a local flight and winds were out of the northeast around 1:35 p.m., MST (20:35Z) - AWOS saying it was 060@8kts - with a visual check of the windsock, that looked accurate. Skies were clear so we taxied out to Runway 11. Take off was good, a little left aileron as we rolled, and we were climbing. Departure was approximately 13:50 p.m., MST (20:50Z).

We headed south, climbing to about 8,500' msl, it got extremely cold up there so I turned east and we descended about 2000 feet as we flew north toward Pueblo Reservoir. We flew over the dam, and then I pointed the airplane west as we flew over the reservoir and along the Arkansas River. About 8 miles out I check the AWOS, and the wind was out of the east 120@5kts. As I continued flying, one of the local pilots on the Unicom asked my location and I gave it - I was northeast over Highway 115 about 4.5 miles away from the airport. Another pilot keyed in and asked for my current location. I checked the AWOS again about 3.5 miles out, at about 21:40Z, just before I set up my 45 degree entry into the pattern, the wind was still 120@5kts. I did notice a jump plane that was descending out of 10,000 ft. and pointed it out to my friend letting him know it was at our 1:00. We had another aircraft in the pattern ahead of us, and two or three behind us. There were two jump ships out, and I'm not sure when or where the jump ship at 10,000 feet came in.

I called my downwind entry, checked the mid-field windsock and wind tee noticing they were favoring runway 11. In front of us, one of the jump planes was turning base. I extended my downwind to give that pilot room and time to land on runway 11. I watched as that aircraft was on final, so I turned base which was extended a little way out. I turned final letting my passenger know that I was going to slip the aircraft a bit which happened to block my view of the small windsock on the right side of the approach to runway 11. I noted the ground speed was slightly stronger in my flare so I just kept holding it off and let the plane bleed its speed thinking it was a little fast from my slip. I landed straight, on the center line, and rolled about 800 feet using rudder to keep it straight and then, before I knew it, the airplane violently swerved to the right. I used rudder but couldn't get in under control. All I can recall at that point was thinking a gust just took us, and it was too late to initiate a "Go Around", and then all I saw was grass and watching the plane rolling over to inverted at approximately 21:45Z or so. I don't remember seeing an experimental airplane passing by, flying low, about 100 AGL so I was told, east bound over the runway, but I did notice the Cessna 172 with an instructor and student aboard that landed on runway 11, wondering why they landed with a tailwind and why they would land with an aircraft upside down just off the runway to their right. At what point did the wind flip around 180 degrees, I thought? I wish I knew, but I think I was in the wind shear. I did not intend to land with a tailwind, it just happened.

I believe the violent swerve to the right caused the left wheel assembly to fail under severe side load, wrenching the brake caliper from the torque plate and locking up the left wheel, as evidenced by the skid mark on the runway. This likely contributed to the nose over.

Please note the attached wind direction, speed, temperature, and dew point during the time I was flying. Approximately, 20:50Z to 21:50Z. Note the wind direction change, velocity spike, and dew point increase at 21:50Z, about the time it would get to the weather station south and east of Runway 11.

This statement is what I can recall to the best of my knowledge.

Gail Schmidt

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

I suspect due to the rapid change in wind direction (see charts attached), there very well could have been wind shear or a strong gust causing the airplane to violently swerve to the right. It felt like the strike of a hand across my face. If the same factor or forces were present today, I don't know if the outcome would be any different. However, if there is a next time, I'll pay more attention to what my ground speed is telling me and initiate a "Go Around" even though there may be traffic in front of me, behind me and what the AWOS had told me a few minutes earlier.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)**Was there Mechanical Malfunction/Failure?** ☒ Yes ☒ No*(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)*

Immediately after incident, it was noted that the tailwheel tire bead was not seated against wheel rim. Tire was flat. No apparent damage to tire. Reason for losing inflation pressure: unknown
Possible contributing factor to loss of directional control.

Total Time/Cycles On Part

unknown Hours

unknown Cycles

Time Since This Part Inspected/Overhauled

unknown Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff***(Convert from pounds, as necessary)*

17 Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT****Was an emergency evacuation of the aircraft performed?** ☐ Yes ☒ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Due to the inverted resting position of the aircraft, gravity was the primary method of exit. One occupant at each cockpit fell on their head.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

02/04/17

mm/dd/yyyy

Name of Pilot/Operator: Gail Schmidt

Signature: _____

-- or --



Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --



Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

GAA17CA125

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Eric Swenson

Date Report Received

02/06/2017