



Photo 1 – Damaged Fuselage and Wing Attach Point (Photo Courtesy of FAA)



Photo 2 – Damaged Left Wing and Collapsed Landing Gear (Photo Courtesy of FAA)