



Photo 1 – Airplane in Grass Area Next to Runway (Photo Courtesy of FAA)



Photo 2 – Airplane’s Left Wing and Fuselage (Photo Courtesy of FAA)



Photo 3 – Separated Hydraulic Brake Line (Photo Courtesy of FAA)



Photo 4 – Tire Marks Leading Off Runway into Grass (Photo Courtesy of FAA)



Photo 5 – Rear View of Left Wing Damage (Photo Courtesy of FAA)