



Photo 1 – Nosed Over Airplane Next to Runway (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)



Photo 3 – Tire Tracks Leading Off the Runway (Photo Courtesy of FAA)