



Photo 1 – View of airplane at about 45° angle to snow (photo courtesy of the pilot)



Photo 2 – View of damaged windshield (photo courtesy of the FAA)