



Photo 1 – Airplane on Runway with Landing Gear Retracted (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Fuselage (Photo Courtesy of FAA)



Photo 3 – Airplane with Landing Gear Extended and Locked, Postaccident (Photo Courtesy of FAA)