



**Photo 1 – View of damage to right wing spar and empennage (Courtesy of FAA)**