



**Photo 1 – View of Bent Right Wing Lift Strut (Photo Courtesy of FAA)**



**Photo 2 – Accident Airplane Floats (Photo Courtesy of FAA)**



**Photo 3 – Right Float (Photo Courtesy of FAA)**