



Photo 1 – Substantially Damaged Firewall (Photo Courtesy of FAA)



Photo 2 – Interior view of Firewall Damage (Photo Courtesy of FAA)