



Photo 1 – View of inverted damaged rudder (Photo courtesy of the FAA)