



Photo 1 – View of Airplane off Runway with Collapsed Nose Gear (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Firewall (Photo Courtesy of FAA)