




**Photo 1 – View of damage to the right wing and aileron (Courtesy of FAA)**



**Photo 2 – View of damage to elevator (Courtesy of FAA)**