



Photo 1 – View of airplane from rear (photo courtesy of the FAA).



Photo 2 - View of fuel streak on right wing (photo courtesy of the FAA).