



Photo 1 – Substantially Damaged Right Elevator (Photo Courtesy of FAA)



Photo 2 - View of Airplane After Runway Excursion (Photo Courtesy of FAA)



Photo 3 – View of Airplane with Extended and Locked Landing Gear Post-Accident (Photo Courtesy of FAA)