



Photo 1 – Overhead View of Accident Airplane and Runway (Photo Courtesy of Edwards County Sheriff's Department)



Photo 2 - Substantially Damaged Fuselage and Wings (Photo Courtesy of FAA)



Photo 3 – Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)