



Photo 1 – Overview of Airplane Accident Site on Runway (Photo Courtesy of FAA)



Photo 2 - Substantially Damaged Fuselage and Engine Mounts (Photo Courtesy of FAA)