

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Othello State: WA

ZIP: 99344 Country: USA

Latitude: 46°47'38.06" Longitude: 119°04'29.01"

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 10/14/2017 Local Time: @ 1:45 PM
mm/dd/yyyy

Time Zone: Pacific

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N8432

Manufacturer: Vincent Himsel

Model: Vans Aircraft RV8

Serial Number: 80296

Year of Manufacture: 2009

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: RV8 - Vansaircraft.com

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1800 lbs

Weight at Time of Accident/Incident: @1680 lbs

Number of Seats: 2 Flight Crew Seats: 1

Cabin Crew Seats: 0 Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☒ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Aero Sport Power	O-360-A2A	0563-SP	11/26/2003	180	142-tach	2.3-tach	n/a
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 03/31/2017
mm/dd/yyyy

Airframe Total Time: 201 Hobbs hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: 1.3lb Halon hand held

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: CATTO 3-Blade

Model: RV8 SN: 0406696

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: n/a

Model: n/a

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: ACK

Model or Part No.: E-04 ELT

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☒ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☒ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☒ Electronic Multifunction Display
☒ Electronic Primary Flight Display
☒ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☒ Other, Specify: AVmap panel GPS, analog ALT, VSI, Tach

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Vincent S. HimslCity: Desert Aire (Mattawa)Fractional Ownership Aircraft: ☐ Yes ☒ NoState: WA ZIP: 99349Country: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Othello MunicipalDistance From Airport Center: 0.3 smAirport Identifier: S70Direction From Airport: 120 degrees trueProximity to Airport: ☐ Off Airport/Airstrip ☒ On Airport/Airstrip ☐ N/AAirport Elevation: 1149 ft. msl**Runway Information**Runway ID: 25 (L/R/C) Length: 4000 ft Width: 75 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☒ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☒ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☒ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Vincent City of Residence: Desert Aire (Mattawa)
 Middle Initial: S State: WA ZIP: 99349
 Last Name: Himsl Country: USA
 Age at time of Accident/Incident: 68 Date of Birth: 1949 mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☒ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☒ 5-point</td> <td>☒ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☒ 5-point	☒ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☐ 3-point	☐ 3-point																
☐ 4-point	☐ 4-point																
☒ 5-point	☒ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer		Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown															
Principal Occupation ☐ Pilot ☒ Other ☐ Unknown		Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance															
Date of Last Medical <u>01/05/2016</u> mm/dd/yyyy																	

Medical Certificate Limitations

Must have available glasses for near vision. Must wear corrective lenses.
 Plus SODA: waiver serial number 30D10835 for defective visual field and acuity right eye

Medical Certificate Special Issuance

n/a

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

10/09/2016
 mm/dd/yyyy

Flight Review Aircraft

Make: Cessna
 Model: 172

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
---	---	--	--

Type Ratings

complex / high performance (retractable landing gear, constant speed prop...)

Student Endorsements (Include dates)

n/a

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	570	201	570	0	38	4	72	0	0	0
Pilot in Command (PIC)	509	201	509	0	35	4	72	0	0	0
Time as Instructor	0	0	0	0	0	0	0	0	0	0
This Make/Model					1	0	0			
Last 90 Days	3	3	3	0	0	0	0	0	0	0
Last 30 Days	1	1	1	0	0	0	0	0	0	0
Last 24 Hours	0	0	0	0	0	0	0	0	0	0

“FLIGHT CREWMEMBER 2” INFORMATION

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: _____

City of Residence: _____

Middle Initial: _____

State: _____ ZIP: _____

Last Name: _____

Country: _____

Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)						
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
Crew Name and Address				Seat Occupied		Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____				☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign				Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No		Total Flight Time at the Time of this Accident/Incident: _____ hrs				
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)						
Name and Address		Seat	Injury	Restraint Type		Inflatable Restraints
First Name: <u>Sharon</u> City : <u>Desert Aire (Mattawa)</u> Middle Initial: <u>M</u> State: <u>WA</u> ZIP: <u>99349</u> Last Name: <u>Himsl</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: <u>rear</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other		☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>M94</u> City: <u>Desert Aire (Mattawa)</u> State: <u>WA</u> Country: <u>USA</u>	Time of Departure Time: <u>1:00 PM</u> Time Zone: <u>Pacific</u>	Destination Airport ID: <u>S70(fuel) then S94</u> City: <u>Colfax</u> State: <u>WA</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	---	---	--

Type of ATC Clearance/Service (Check all that apply)			
☒ None ☒ VFR	☐ Special VFR ☐ IFR	☐ Special IFR ☐ VFR On Top	☐ VFR Flight Following ☐ Traffic Advisory
☐ Cruise ☐ Unknown / NA			

Airspace where the accident/incident occurred (Check all that apply)			Altitude of In-Flight Occurrence: <u>1140</u> ft msl
☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply)	Weather Observation Facility
☐ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	Facility ID: <u>KWAMATTA4</u> Observation Time: <u>1:00 PM</u> Time Zone: <u>Pacific</u> Distance from Accident Site: <u>35</u> nm Direction from Accident Site: <u>244</u> degrees true
☐ Company ☐ Military ☒ Internet ☒ None ☐ Unknown	

Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night
---	---

Sky/Lowest Cloud Condition ☒ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown	Temperature: _____ (C) or <u>54</u> (F) Dew Point: _____ (C) or <u>37</u> (F) Altimeter Setting: <u>30.51</u> in. Hg or _____ MB
Lowest Cloud Condition Height <u>clear</u> ft agl	Ceiling Height <u>clear</u> ft agl	

Wind Direction ☐ Variable -or- Direction: <u>345</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>@11</u> kts	Wind Gusts ☐ Not Gusting -or- Speed: <u>unknown</u> kts	Visibility <u>Clear</u> miles RVR: <u>Clear</u> feet RVV: <u>Clear</u> miles Density Altitude: <u>519</u> ft
--	--	--	---

Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☒ N/A ☐ Unknown	Type of Precipitation (Check all that apply)	Restriction to Visibility (Check all that apply)
☐ None ☐ Rain ☐ Snow ☐ Hail ☐ Rain Showers	☐ Drizzle ☐ Ice Pellets ☐ Snow Pellets ☐ Snow Grains ☐ Ice Crystals	☒ None ☐ Blowing Dust ☐ Blowing Sand ☐ Blowing Snow ☐ Blowing Spray ☐ Dust
	☐ Freezing Rain ☐ Snow Shower ☐ Ice Pellets Shower ☐ Freezing Drizzle	☐ Fog ☐ Ground Fog ☐ Haze ☐ Ice Fog ☐ Smoke ☐ Unknown

Icing Forecast	Icing Actual	Turbulence
Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown	Amount ☒ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown	Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence
Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown	Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☐ Unknown	Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

Hanford minimum altitude request (1800'MSL). Yakima Training Center Restricted Airspace NOTAMs. However, relevant VFR for intended route (M94-S70-S94) and altitude of flight (@3500'MSL) = none.

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

N8432:

Ruptured starboard fuel tank. slight deformation of Starboard wing Spar. Gash on bottom of Starboard Flap. Broken fiberglass elevator tip.

S70:

Inner PAPI unit broken off (presumably destroyed) at Frangible Connectors.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

I departed Desert Aire Regional Airport (M94) at @1PM for VFR flight to Colfax (Port of Whitman S94) with a planned stop at Othello Municipal (S70) for fuel. After refueling (15.5 gallons) at Othello Municipal Airport (S70) I proceeded to takeoff runway 25 for a left downwind departure towards the east (Colfax). I applied full power and at approximately 400 ft. I raised the tail. The aircraft reacted normally but then began to weather vane into the approximately 11 mph crosswind coming from the south. Unable to recover, almost airborne but with the side of the airport sloping downward, I proceeded to lift off. Looking out my canopy to the left, I saw the outer Precision Approach Path Indicator (PAPI) and remember saying to myself "Good! I will miss the PAPI". I left the runway and realized I was still on the ground so I applied back pressure to the control stick. The RV8 lifted off but I then heard a bang that sounded as if my landing gear had hit a rock 'or something'. At about 100' AG feet my wife in the back seat said she smelled gas. We both looked out and saw fuel spewing out from underneath my right wing. I immediately switched fuel to my left tank and began to circle around until the fuel completely emptied from the ruptured tank.

While circling the airport, I decided to land immediately but my problem was I didn't know what I had hit and what damage it had caused to my landing gear. It is a low wing airplane so I couldn't see underneath. I tried to contact someone on the ground hoping they had their radio on but got no response. With no one to talk to on the ground, not knowing the condition of my landing gear or my wing, and with my wife aboard I dialed in 121.5 (the emergency radio channel) and declared an emergency.

At this point I had enough of my wits about me to verify the left tank was full of fuel (2 hrs.) and the airplane was flying...for the moment. With the assistance of ATC, I decided to fly to Grant County International (KWMH) as they had emergency response equipment.

Arriving at Grant County, I received permission to circle the tower so that the controllers could look and see if my landing gear looked 'OK'. They said that from what they could tell, it did look OK. My RV8 has fiberglass wheel pants, so any damage would be obvious so I felt pretty confident (and relieved) that I was safe to land.

I landed at Grant County, taxied over to the terminal and shut down the engine. We were on the ground.

The next day, Sunday October 15, 2017, my friend flew me to the Othello Airport so we could see what happened. Up until this point I was confident I had not hit the PAPI. We walked over to where I thought I had taken off and saw nothing. Walking further towards the runway numbers we saw an orange plate laying in the dirt and then the upturned PAPI broken off at the frangible connector.

Walking further down towards the start of runway 25, I saw what looked like my 3 tire tracks. Taking pictures I realized that when I had taken off, I had noticed the outer box of a two box system. I missed the outer box but hit the inner box.

As this was a safety issue, I called the airport manager and told him what happened. He arrived about 10 minutes latter and I gave him my information.

We continued on to Grant County Airport where my RV8 was parked and did an inspection of the damage. Both my friend and I are experienced RV builders and I have a repairman certificate for my airplane.

The starboard fuel tank is punctured and needs to probably be replaced. The starboard flap is gouged but is possibly repairable. The starboard elevator fiberglass tip needs to be repaired or replaced. The most critical components (wing spar, wing assembly, etc.) appears undamaged most likely due to the frangible connectors on the PAPI box working as designed.

I determined that my RV8 was airworthy enough to fly it back to Desert Aire Regional Airport (M94) but just to make sure, I left it at Columbia Pacific Aviation for their A&P to inspect.

Note: It turned out the crack had been 'compromised'



RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Recommendations:

Pilots be reminded of the potential for take off ground loop on high power high performance tail dragger airplanes when the tail is lifted before adequate rudder authority.

How could this accident have been prevented:

All I can say is that somewhere in my past I got the idea that raising the tail as quickly as possible was what one did with a tail dragger. I have practiced not doing that, but on this occasion, forgot. I believe I was entering a ground loop. I recovered but not in time to avoid going off the runway and in the process impacting the PAPI on take off. 20/20 hindsight, I should have departed from the extreme north side of the runway providing more room to recover.. I should have waited until I felt the control stick being pulled forward before raising the tail.

Conversely, I do not regret lifting off even though going off the runway. The airport is elevated and surrounded by grass land / desert. More importantly If I had chopped power and hit the brakes, I would have still hit the PAPI but my RV8 would now be resting in a 20 gallon pool of 100LL.

The take off aside, I did some things correctly. I recovered from the ground loop, flew the airplane, declared an emergency and got my wife and I safely on the ground. But I am haunted by the fact that had I performed a proper take off, I would have had an uneventful enjoyable VFR flight to Colfax.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

n/a

**Total Time/Cycles
On Part**

n/a _____ Hours

n/a _____ Cycles

**Time Since This Part
Inspected/Overhauled**

n/a _____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

40 _____ Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure**

none

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Normal exit, pilot first then passenger. Fire Truck and personnel monitoring. Note: no fuel remaining in ruptured tank.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Aircraft Information:

Reason for ELT inactivation: ELT system does automatic check (beeps) on power up so it was functioning so reason it did not activate is because it did not register minimum required force.

Flight Itinerary:

I considered this flight a local flight and did not file a VFR flight plan.

Weather at Accident Site:

Used Historical weather from listed weather station as I didn't record weather data in my log book. The weather station listed is the one I used prior to take off from Desert Aire. I also used 'AVARE' and 'METAM' (android apps) for preflight information. There is no weather station located at Othello Municipal (S70). I planned to use the AWOS at Pullman Regional (PUW) for arrival info at Colfax.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE**Date of this Report**10/23/2017

mm/dd/yyyy

Name of Pilot/Operator: Vincnet S. Himsl**Signature:** _____-- or -- ☒ Check here to electronically sign this document**If a Person Other than Pilot/Operator is Filing Report****Name:** _____**Title:** _____**Signature:** _____-- or -- ☐ Check here to electronically sign this document**FOR NTSB USE ONLY****NTSB Accident/Incident No.**

GAA18CA014

Reviewed by NTSB Regional Office

GAAID

Name of Investigator

HICKS, M.

Date Report Received

23OCT2017