



Photo 1 – View of damaged right wing (photo courtesy of the FAA)




Photo 2 – View of separated rudder cable (photo courtesy of the FAA)



Photo 3 – View of three sections of separated rudder (photo courtesy of the FAA)