



Photo 1 – Nosed Over Airplane with Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)



Photo 2 - Substantially Damaged Left Wing (Photo Courtesy of FAA)