



Photo 1 – View of damaged fuselage (Photo courtesy of the FAA)



Photo 2 – View of wrinkled fuselage aft of the main landing gear (Photo courtesy of the FAA)



Photo 3 – View of damaged engine mount (Photo courtesy of the FAA)