



Photo 1 – View of damage to both wings (Photo courtesy of the FAA)



Photo 2 – View of airplane during touch-and-go landing (Photo courtesy of the passenger video)



Photo 3 – View of airplane in ground effect just before aborted takeoff (Photo courtesy of passenger video)