




Photo 1 – View of damaged fuselage (Photo courtesy of the flight school)



Photo 2 – View of damaged floorboard (Photo courtesy of the flight school)