



Photo 1 – View of collapsed right landing gear (Photo courtesy of the FAA)




Photo 2 – View of damaged internal structure (Photo courtesy of the FAA)